



EASA Certification Information

No.: 2018 - 10
Issued: 28 May 2018

Subject: Revocation of various certificates upon request for surrender

Authorisation No:

| Authorisation | Description | P/N | Date of last issue | DDP ref. |
|-------------------------|-------------|--------------|--------------------|-------------|
| EASA.21O.046 | VIR-4000 | 822-1467-() | 26/05/2004 | 523-0790046 |
| LBA.N-O.10.922/095 JTSO | NAV-4500 | 822-1579-() | 31/01/2003 | 02-05A |
| LBA.N-O.10.985/011 JTSO | NAV-4000 | 822-1465-() | 20/02/2003 | 02-05A |

Holder of the Certificate: Rockwell Collins, Inc.
 400 Collins Road, NE
 52498 Cedar Rapids
 USA

Background: On the dates mentioned in the table above EASA and LBA issued the specified authorisations to Rockwell Collins, Inc.
 On 22 November 2017 Rockwell Collins, Inc. submitted to EASA a request for surrender of all the authorisations listed above. Rockwell Collins, Inc. informed EASA that several of their equipment types are not in full compliance with the applicable ETSO and JTSO standards but that they fully comply with their FAA TSO Authorisations according to the statement of Rockwell Collins, Inc. Additionally, Rockwell Collins, Inc. confirmed that their installers have been notified of the surrender of the authorisations listed in the table.

In accordance with the applicable EASA administrative procedures¹, EASA decided to revoke the above mentioned authorisations. EASA has submitted the decision to revoke all above mentioned authorisations to the authorisation holder on 28 May 2018.

Contact: Any request, query or comment should be sent to:

European Aviation Safety Agency
 Parts & Appliances Section
 Postfach 10 12 53
 D – 50452 Köln
 E-Mail: etsoa@easa.europa.eu

¹ EASA procedure PR.TOC.00001 on Transfer or surrender of a product certificate (<https://www.easa.europa.eu/document-library/certification-procedures/transfer-or-surrender-product-certificate>)