



EASA Certification Information

No.: 2008 - 07

Issued: 27th November 2008

Subject: Revocation of Supplemental Type Certificate LBA TA0533 for Boeing 757-200 "Installation eines Zonal Drying System" upon surrender by Lufthansa Technik AG

Supplemental Type Certificate No: TA0533
Issue date: 15th October 2002
Issued by: Luftfahrt-Bundesamt, Germany
Holder of the Certificate: Lufthansa Technik AG

Background: The request by the current Holder to surrender its Supplemental Type Certificate TA0533 has been accepted by EASA as of 3rd November 2008.

In accordance with the applicable EASA administrative procedures¹, upon acceptance of surrender, the aforementioned STC has been revoked by EASA as of 24st November 2008.

Contact: Any request, query or comments shall be sent to:

European Aviation Safety Agency
Attn. Susanne Blischke
Postfach 10 11 53
D – 50452 Köln
E-Mail: certification.information@easa.europa.eu

¹ EASA procedure C.P105-00 on Transfer and Surrender of Certificates
http://www.easa.europa.eu/home/c_intwrkproc.html