



## EASA Certification Information

**No.:** 2018-05  
**Issued:** 05 April 2018

**Subject:** Revocation of various certificates upon request for surrender

**Authorisation No:**

ETSOA No.	Description	P/N	Date of last issue	DDP ref.
EASA.21O.459 REV. A	V1R1 Personnel Parachute	V1R1-O-01( ) / R-01 ( )	23/04/2012	DDP-V1R1
EASA.21O.10018466	Dual Harness Reserve Parachute Type TD400	TD400	23/04/2012	01/DDPTD400
EASA.21O.10018467	Personnel Parachute Omega ( ) / Quick ( )	OMEGA ( ) / QUICK ( )	23/04/2012	OMEGA/QUICK

**Holder of the Certificate:** **Firebird GmbH & Co. KG**  
**Am Tower 16**  
**54634 Bitburg**  
**Germany**

**Background:** On the dates mentioned in the table above EASA issued the specified authorisations to Firebird GmbH & Co. KG. In 2017 Firebird GmbH & Co. KG sold its design organisation to Firebird USA LLC. On the 10 July 2017 FAA issued TSO authorisations to Firebird USA LLC for the above mentioned designs under the condition that Firebird USA LLC will be fully responsible for continued operational safety responsibilities for all articles previously manufactured by Firebird GmbH & Co. KG.

On 19 February 2018 Firebird GmbH & Co. KG submitted to EASA a request for surrender of all the authorisations listed above.

In accordance with the applicable EASA administrative procedures<sup>1</sup>, EASA decided to revoke the above mentioned authorisations. EASA has submitted the decision to revoke all above mentioned authorisations to the authorisation holder on 05 April 2018.

**Contact:** Any request, query or comment should be sent to:

European Aviation Safety Agency  
 Parts & Appliances Section  
 Postfach 10 12 53  
 D – 50452 Köln  
 E-Mail: etsoa@easa.europa.eu

<sup>1</sup> EASA procedure PR.TOC.00001 on Transfer or surrender of a product certificate (<https://www.easa.europa.eu/document-library/certification-procedures/transfer-or-surrender-product-certificate>)