



EASA Certification Information

No.: 2015 - 11
Issued: 14 December 2015

Subject: Revocation of EASA ETSOA No. EASA.IM.210.663 due to bankruptcy of Hoover Industries and termination of their TSO authorization

ETSO Authorisation No: EASA.IM.210.663

Issue date: 11 May 2007

Issued by: EASA

Holder of the Certificate: Hoover Industries
7260 N.W. 68th Street
33166-2014 Miami, Florida
USA

Model: Flotation vest FV-35F

Part Number: 3505-() () () ()

Background: FAA informed EASA that FAA has terminated the TSO authorization of Hoover Industries due to their bankruptcy and no further articles can be manufactured using this authorization.

In accordance with the applicable EASA administrative procedures¹, EASA decided to accept the surrender of the aforementioned authorisation. EASA has submitted the decision to revoke ETSOA No. EASA.IM.210.663. on 14 December 2015.

Contact: Any request, query or comment should be sent to:

European Aviation Safety Agency
Parts & Appliances Section
Postfach 10 12 53
D – 50452 Köln
E-Mail: etsoa@easa.europa.eu

¹ EASA procedure PR.TOC.00001 on Transfer or surrender of a product certificate (<http://easa.europa.eu/certification/internal-working-procedures.php>)