

FAQs:

Production Organisations (POA), Applications for organisations, Certification of products and organisations

Question:

What else do I need to know on the Surveillance Fee for holders of EASA Production Organisation Approvals?

Answer:

After the issuance of the Production Organisation Approval, EASA will levy per period of twelve (12) months an annual surveillance fee in accordance with **Table 10 of Part I of the Annex** to this Regulation (**refer to Surveillance fee**), for the purpose of maintaining the certificate. The first 12-month period starts on the date on which the certificate is issued.

The revised Regulation introduces two new criteria to determine the applicable fees:

Number of related staff

- Staff related below 100
- Between 100 and 499
- Between 500 and 999
- Between 1 000 and 4 999
- Between 5 000 and 20 000
- Over 20 000

Highest Priced Product

- Below EUR 5 000
- Between EUR 5 000 and 100 000
- Above EUR 100 000

"Number of related staff": The information must reflect the number of staff, or in case of an initial approval the intended number of staff, for the complete activities to be covered by the approval and therefore must include also any associated administrative staff.

"Highest Priced Product": Value (as mentioned in the relevant manufacturer's list prices) of the most expensive product, part or non-installed equipment that is included in the approved POA scope of work (capability list) of the EASA POA holder.

The amounts referred to in **Part I of the Annex** shall be indexed, with effect of 01 January each year, to the inflation rate in accordance with the method set out in **Part IV of the Annex**.

Please note that the above summary of the related provisions of the Fees & Charges regulation is provided for convenience only. If, at any time, there is a discrepancy, inconsistency or conflict between the information provided above and information in the Commission Implementing Regulation (EU) 2019/2153, the latter shall prevail.

Last updated:

13/08/2020

Link:

https://www.easa.europa.eu/sv/faq/117090